



Whitley County Health Dept Community Environmental Rating Report

Today's Date 10-11-18 Report for Churubusco - South Side (110 Residences)

#of non-compliant systems - determined as % 71 % non-compliant (78 homes)

of citations = determined as a % 6% complaints, 5 written since 1990, 1 visual complaint 1998

Information received from community At least 6 homes have not been able to sell because of failed septic inspections.

Physical site assessment 1998, I personally witnessed these areas draining to the newly constructed ponds on the C & A Property.

Prior testing data No water or dye testing has been performed. Homeowner confirmation of discharging systems.

Written Summary: There has been a total of five repairs in the past. Since 1998 the County and IDEM have been aware that Circle Drive, Carlin Court, Orchard lane, and 375 North all drain their sewage to the Eel River, from Whitley County. This is the largest discharge of un-treated sewage in the County.

Overall Assessed Score (1-5): / _____